

**LIST OF REPORTED SPILLS OF OIL**  
**DEC 1999 – DEC 2001**

<b>Date</b>	<b>Incident/Location</b>	<b>Quantity/Type of Oil</b>	<b>Action Cleanup</b>
Dec 8 1999	Less than 5 gallons of contaminant spilled to water in the basin at South Riding Point, from a tugboat, owned by SRPHL.	5 gallons/Oily bilge	Corexit dispersant applied via an hand-held sprayer to the extended masses, much of the slick was corralled with Slickbar boom, and absorbent pads applied to surfaces to recover contaminant
Feb 29 2000	An oil slick, (of <5 gallons), of unknown source, was noted off South Riding Point, beyond the jetty, and moving towards the west from the jetty	Less than 5 gallons/Aged diesel, or bunker fuel	Corexit dispersant was applied and the mass disturbed with the actions of work boats
Mar 19 2000	Marine and coastal contamination with ca 20 gallons of oil, from an unknown source, soiling the rocky intertidal coast of McClean's Town	Ca. 20 gallons/ Aged diesel, or bunker fuel	As much of the viscous mass was removed from the seawalls as possible.
Mar 27 2000	A report fro Great Harbour Cay, that numerous tar bails, from unknown source, were collected on a sandy beach	"Buckets" of Tar bails sealed with aged diesel, or bunker fuel, or crude	Tar bails were collected off the beach
Mar 30 2000	A report that an unknown quantity of gasoline was spilled to sea at the dock at Elizabeth Harbour, Great Exuma	Unknown/ Gasoline	Absorbent boom was applied to remove some of the contaminant; and evaporation allowed to take place for the remainder
Apr 19 2000	A report of marine contamination, with an unknown quantity of oil, at the rocky coasts of Pinder's Point.	Unknown//Aged lubrication oil	No action taken
Jun 5 2000	A repeat of the 19 March 2000 incident, at the sandy beach of Pelican Point	Unknown/ Aged diesel or bunker fuel	No action taken
Jul 24 2000	A repeat of the 19 March 2000 incident at the sandy beach of Pelican Point	Unknown/ Aged diesel, or bunker fuel	Tar bails and patties were removed from the beach
Sep 25 2000	A report of "1 litre" of oil escaping from a cruise ship near to Coco-Cay	1 litre/ Ages lubricant oil	Dispersant applied
Nov 6 2000	A report of oil contamination by an unknown quantity, from a land-based source at Great Harbour Cay	Unknown – Aged lubricant oil and bunker fuel	Not known – Suggestions have been made for actions by DEHS and responsible parties
Nov 27	A major spill of > 5 barrels of bunker fuel from the BORCO jetty, and affecting the coast at Lewis Yard/Pinder's Point	>5 barrels of bunker fuel	The sandy beach was cleaned manually' the cobble/ rocky beach/ shore was cleaned with absorbent pads, given a light cover with Corexit dispersant, and left for nature attenuation
Dec 5 2000	A report of episodes of marine contamination with small quantities of oil from various vessels at the Morgan's Bluff Harbour at North Andros	Unknown – Aged diesel bunker fuel and oily bilge	Dispersant applied as only action
Jan 2001	A report of a sighting of a spill of an unknown quantity of oil, from and unknown source off the NW coast of New Providence	Not known	No oil confirmed.

Feb 5 2001	A report of a sighting of a spill of an unknown quantity of oil from an unknown source in the vicinity of the Bahamas Reef Boulevard, Lucaya, Grand Bahama	Unknown/Not Known	No oil confirmed
Feb 13 2001	A report of land contamination with an unknown quantity of oil belonging to BEC at South Bimini	Unknown – Aged lubrication oil and bunker fuel	No action taken
Feb 15 2001	A report of the incident of 30 March 2000 involving <100 gallons of oil from a pleasure craft at Elizabeth Harbour, Great Exuma	Less than 100 gallons diesel oil	Same action as before
Feb 23 2001	A report of an oil slick of unknown quantity from a tanker at the Clifton Pier docking facility	Unknown – Bunker fuel	Weather conditions prevented at sea actions
Feb 27 2001	A report of the earlier report and finding in another part of the canal network	Unknown Diesel fuel	No action taken
Feb 27 2001	Note taken of several instances of small gray sheen along the canal system in Lucays, Grand Bahama attributable to spills during fueling exercises at berth	Unknown – Aged diesel fuel	No action taken
Mar 8 2001	A report of an oil slick off Freeport Grand Bahama	Not oil really a large school of “sea thimble”	No action taken
Mar 8 2001	A report of an oil slick off New Providence	No further information available	Not known
Apr 6 2001	A report of an episode of oil contamination at the pebble beach to the west of SRPHL oil transshipment terminal	No evidence of contamination found	None taken
Apr 30 2001	A report of an oil slick of <100 gallons at sea, tending from east to west at sea from SRPHL origin	Less than 100 gallons – Aged diesel, or bunker fuel	Dispersant applied
May 14 2001	A report of an oil slick in the canals of Lyford Cay of unknown quantity and of unknown origin	Unknown – Aged and freshly applied diesel fuel	A contractor has applied absorbent peat
May 17 2001	A repeat of the incident of Dec 5 2000 at Morgans Bluff North Andros	Unknown – Aged diesel or bunker fuel	No action taken
May 19 2001	A report and photographs of an oil slick of ca 100 gallons (probably) from a sandmining operation in the vicinity of the sandy beach at Fortune Bay, Lucaya, Grand Bahama	Ca 100 gallons/ Diesel or bunker fuel	No action taken. A report was sent to the Permitting Agencies for the project.
May 23 2001	A report of several hundred gallons of oil spilled to water off Lewis Yard, Grand Bahama, during a storm from a puncture in the fuel tank of a tanker	“Hundreds” of gallons/Bunker fuel	Dispersant applied at sea manual cleaning effected at the 5 miles coast of Mack Town to Pinder’s Point.. May 24 <sup>th</sup> to August 6th
Jun 3 2001	A repeat of the incident of Mar 30 2000, where ca 200 gallons of oil spilled to water at Elizabeth Harbour, Georgetown, Great Exuma, during a refueling exercise	Ca 200 gallons/ Diesel fuel	Absorbent boom and pads deployed for some collection

Jun 8 2001	A report of unknown quantities of crude oil spilled to ground, at SRPHL from two (2) leaking tanks	Unknown/Crude oil	Seawater applied to the tanks to minimize loss of oil; as possible the oil has been transferred from the tanks, oiled soil has been partially scooped up and placed into oil sludge pits on site
Jun 27 2001	A repeat of the incident of Dec 8 1999 where ca 1 gallon of oily bilge was discharged to water from the SRPHL jetty, Grand Bahama	Ca 1 gallon water containing hydraulic oil	Corexit dispersant was applied
Jun 27 2001	A report of small patches of an oil slick from an unknown source, discovered in the harbour at Marsh Harbour	Unknown/ Aged diesel or bunker fuel	No action taken
Jun 24 2001	A report of a spill of an unknown quantity of oil spilled to the deck of a vessel then to water at the FOCOL oil discharge port at the Freeport Harbour	Unknown/ Jet aviation fuel	Corexit dispersant applied. A report was sent to the Permitting Agencies for this and similar operations
July 2 2001	A report of an oil slick of unknown quantity of oil, and from an unknown source, in the basin at SRPHL, Grand Bahama	Unknown/No oil discovered	No action taken
July 26 2001	A report of a slick of an unknown substance and from an unknown source, noted off Lewis Yard, Grand Bahama	No contaminant detected	No action taken
August 7 2001	A report of a 1-2 mile oil slick in water, as derived from a vessel at the jetty at Clifton Pier, Nassau	No further information available	No further information available
August 2001	A report of an oil slick of unknown quantity of fuel, from an unknown source, discovered off Arawak Cay, Nassau	Unknown/ diesel or bunker fuel	"A contractor has cleaned up the spill"
August 13 2001	A repeat of the incident of 8/December 1999, where ca 30 gallons of oily bilge was discharged to water from a tug boat, in the basin at SRPHL.	Ca 30 gallons/Water with hydraulic oil	Corexit dispersant applied, boom deployed in conjunction with a suction hose from a vacuum truck adsorbent pads were applied.
August 15 2001	A report of episodes of oil slick noted in the water at Williamstown Beach, following the collection of clients for snorkeling trips from the beach	Unknown/Aged diesel fuel	A report was issued to the beach resort and to the management of the snorkeling trips
August 17 2001	A report of an episode of yellowing of seawater at the beach at Williamstown Beach	A persistent (hrs) yellow dye-colour could be detected in the water; the contaminant could not be identified.	No action taken

August 27 2001	A report from an anonymous source was received with indications that frequent episodes of water contamination were occurring at the Bradford Marina and Freeport Shipcare Facility, sites, where much mechanical and cleaning work was being effected at the water's edge		Reports have been sent to the Permitting Agencies
September 7 2001	A report of expansive and patchy oil slicks from an unknown source were sited in the canal network near to the Dolphin Sanctuary, Lucaya, Grand Bahama	Unknown /Aged diesel fuel	Floating boom was applied to protect the Dolphin Sanctuary
September 7 2001	-ditto, at other parts of the canal network and where from the air, numerous (potential) sources of fuel spills could be identified – marinas home berths, fuel storage, boat washing units and home servicing of boats	-ditto-	Reports were sent to the permitting Agencies
September 10 2001	A report of the event of 27 June, 2001, where ca 5 gallons of oily bilge was discharge to water at the SRPHL jetty	Ca 5 gallons/water with lubrication oil	No action taken
September 10 2001	A report of a sustained episode of oil leaking to ground at a fueling station in Murphy Town, Abaco	Aged bunker fuel	No action taken Reports have been issued to the Permitting Agencies
September 10 2001	A report of a sustained episode of an oil slick off Clifton Pier, thought to be from BEC's outfall	Aged diesel fuel	No action reported
October 4 <sup>th</sup> 2001	A report of a spill of an unknown quantity of oil to ground at a work station on BORCO's property	Unknown/Crude oil	
December 2001	A repeat of the incident of 8 June 2001, where an unknown quantity of oil spilled to ground leaking from a transfer line, at SRPHL	Unknown/Crude oil	Some of the oil was recovered; the oil soil was scooped and transferred to the oil sludge pit on site